



EXPLANATION

- 36
Well used for control. Number indicates the dewatering, in feet
- 40 —
Line showing the dewatering, in feet
- Contour interval, 20 feet
- 
Outcrop of the Carrizo sand
- 
Fault dashed where approximately located
U, upthrown side; D, downthrown side

Base adapted from general highway map of Texas Highway Department

Scale: 0 1 2 3 4 Miles

Geology of the Carrizo sand by A.N. Sayre and S.F. Turner

DEWATERING OF THE CARRIZO SAND, DIMMIT COUNTY, TEXAS, 1929 - 57.